ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0070, W0087, W0085, W0089	NA	Shanarinagar
Segment No.	**Total Length (m)**	
6/C-W0070/S062304	346.37	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	91.77	77.635269	13.072592	77.635267	13.071762	W0070	W0082
2	90.95	77.634893	13.071771	77.634902	13.072593	W0070	W0082
3	91.98	77.634538	13.072610	77.634526	13.071779	W0070	W0082
4	71.67	77.634574	13.072642	77.635234	13.072627	W0085	W0089

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to road & drain at Shanarinagar in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	3000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to road & drain at Shanarinagar in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-15-000036
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/27/2016-17	05/05/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/07/2016	29/07/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Y R SRIDHAR		0.00
Phone No.	**E-Mail ID**	
9845182420		

Field Inspection Details

Number of Trees	Any Other Information	Name
4		KRISHNAPPA
Date of Inspection	**Remarks**	
21/02/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0070, W0087, W0085, W0089

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	21/02/2017	23/03/2017	COMPLETED
SE	VASU K M	21/02/2017	23/03/2017	COMPLETED
EE	MOHAN DAS HT	21/02/2017	23/03/2017	COMPLETED
AEE	J N LOKESH	21/02/2017	23/03/2017	COMPLETED
AE	KRISHNAPPA	21/02/2017	23/03/2017	COMPLETED
AE	KRISHNAPPA	21/02/2017	23/03/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0070, W0087, W0085, W0089